



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 001

Direction: Northeast

Subject: Terra operator removing a tree stump in Area 1.

Date: September 21, 2009

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 002

Direction: Southwest

Subject: Pin flags denoting the node points from which Arcadis collected four Area 1 samples.

Date: September 23, 2009

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 003

Date: September 23, 2009

Direction: Down

Photographer: Michael Browning

Subject: Arcadis personnel collecting sample material from a node point in Area 1.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 004

Date: September 23, 2009

Direction: Southeast

Photographer: Michael Browning

Subject: Terra workers installing sheet piling along the eastern shore of Island 1.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 005

Direction: East

Subject: Terra operator excavating material from Island 1.

Date: September 25, 2009

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 006

Direction: South

Subject: Arcadis workers using a GPS unit to locate and flag a node point that Arcadis will sample in Area 1.

Date: September 29, 2009

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 007

Direction: Southwest

Subject: Re-excavated Grid 6 of Area 1.

Date: October 2, 2009

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 008

Direction: Northeast

Subject: Terra operator placing river run rock along the shoreline of Area 1.

Date: October 2, 2009

Photographer: Michael Browning



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 009

Date: October 2, 2009

Direction: East

Photographer: Michael Browning

Subject: Terra workers laying geofabric onto which a Terra operator will place river run rock.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 010

Date: October 5, 2009

Direction: Northeast

Photographer: Jay Rauh

Subject: Terra performing river bank restoration.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 011

Date: October 13, 2009

Direction: Northeast

Photographer: Jay Rauh

Subject: Rocks and biologs in the river, as well as JFNew at work.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 012

Date: October 21, 2009

Direction: Northeast

Photographer: Michael Browning

Subject: Terra conducting restoration activities in Area 1.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 013

Date: October 28, 2009

Direction: North

Photographer: Michael Browning

Subject: Arcadis personnel collecting Sample TS20338 from Grid 4 of Area 5A.



Site: Allied Paper Plainwell No. 2 Dam Removal Action

Photograph No.: 014

Date: November 3, 2009

Direction: West

Photographer: Jay Rauh

Subject: Terra removing sheet piling and turbidity curtain in Area 3A and spreading topsoil over excavated sections of Area 4A.

I:\WO\START3\763\41496

763-2A-AFYD